



Effective Multi-tap Transformer Measurement using a Scanner and the Agilent 4263B LCR Meter

Application Note 1224-5



Agilent Technologies

Introduction

With the progress of recent electronics equipment and digital networks, production amounts are increasing of the transformers which contribute to equipment miniaturization, low power dissipation and higher quality. Therefore, improvement of select estimate efficiency is required at the production line or incoming inspection. Noticed recently, improvement of estimation efficiency is required for pulse transformers which are used in LAN or ISDN digital networks, and for multi.-tap transformers with three or more pole taps, such as switching power transformers. This application note shows an effective multi-tap transformer measurement using a scanner and the Agilent 4263B LCR meter.

Agilent 4263B Transformer Measurement Capability

The 4263B LCR meter is a low price instrument which measures the fundamental parameters of LCR components with speeds as fast as 25ms, at frequencies of 100, 120, 1k, 10k and 100kHz. In addition, with option 001, the 4263B measures turns ratio (N), mutual inductance (M) and dc resistance (DCR) which are required for transformer measurement. Figure 1 shows a 4263B simple block diagram for L, M, and DCR measurement.

For example, in the inductance-turns ratio (L-N) measurement, an ac voltage is applied at the Hcur terminal. Self-inductance value (L1) is calculated from the measured values of V1 and I1. Turns ratio (N) is automatically obtained from the ratio of measured values V1 and V2 (discriminating the polarity simultaneously).

In the dc resistance (of L-DCR) measurement, the applied voltage at the Hcur terminal is dc. Dc resistance value (DCR1) is calculated from the measured values V1 and I1.

There are, however, the following limitations when using the measurement connection.

- Only primary self-inductance and dc resistance of the transformer can be measured. For the secondary values, the transformer connections must be changed.
- Turns ratio must be 0.9 or more (In the case of less than 0.9, the measurement is not performed due to saturation of internal circuitry).

Agilent 16060A transformer test fixture can be used to overcome these limitations. By changing the external switch of this fixture, connections to the transformer are changed and thus both primary and secondary parameters and turns ratio can easily be measured. Figure 2 shows the simple block diagram of the 16060A.




Figure 1. Agilent 4263B block diagram for L, M, and DCR measurement




Figure 2. Agilent 16060A block diagram

Multi-Tap Transformer Measurement Using a Scanner

Multi-tap transformers having two or more poles can be measured with the 4263B and a scanner.

(A) System configuration

Figure 3 shows the system configuration for measuring a multi-tap transformer that has 4 taps.

The Agilent 3488A switch/control unit with a 4 x 4 matrix switch module (Opt. 013) is used. Option 013 offers highly flexible switching, and any combination of 4 input channels may be connected to any combination of 4 output channels. Thus option 013 is suitable for testing the multi-tap transformer. Figure 4 shows the hardware configuration of the 4 x 4 matrix switch module.




Figure 3. System configuration for multi-tap transformer




Figure 4. Option 013 4 x 4 matrix module

(B) System construction recommendations

When constructing the system, the following points must be considered to assure the measurements are as precise as can be. (See figure 5)

1. Make measurement cables as short as possible. The parasitic inductance and resistance of measurement cables make a large contribution to measurement error. For recommendable length, conductive wire inductance value must be 1/10 or less than the measured inductance value (similarly conductive wire resistance).

2. Configure into a shielded 2 terminal configuration, to prevent the influence of external noise or stray capacitance.

3. Connect the low terminals close to the transformer.

In the 4263B transformer measurement, the primary and secondary inductors' low terminals of the transformer must be connected together. When using a scanner, these connections should be close to the transformer under test. If connecting at a far point from the transformer (for example, input point of scanner module), low side wire resistance would contribute to increase measurement error.




Figure 5. System construction

(C) Measurement procedure

All measurements of the multi-tap transformer, self-inductance, dc resistance, and turns ratio, can be measured with only one connection by using the sample program shown at the end of this note (for HP 9000 Series 300 Controller). Figure 6 show the flow chart of the sample program.




Figure 6. Flow chart of sample program

This program executes the open and short corrections and displays each measured value of each tap of the transformer. If turns ratio measurement cannot be made due to the condition that turns ratio must be 0.9 or greater, the scanner will be automatically changed and the measurements re-done. This program can be modified to match other systems or conditions.

The following steps outline the program procedure:

Step 1. Run the program. The following message is displayed on the controller's display.

Selection (1) Measurement (2) Correction ?
Type number and press RETURN key

At this point, select the measurement directly, or first the measurement of correction data. To execute the measurement, type 1 and press RETURN key on the controller (Go to step 4). To measure the correction data, type 2 and press RETURN key on the controller.

Step 2. If the measurement of correction data in step 1 was selected, the following message is displayed on the controller's display. The open correction data of each channel of the scanner (CH.0-CH.3) is now measured.

CH.0 Open measurement
Open test terminals of CH.0
Start open meas. (2) Skip CH.0 open meas?

Type number and press RETURN key

To measure the open correction data, set all channels to the open condition as shown in figure 7. Then, type 1 and press RETURN key on the controller. Open correction data of channel number 0 (CH.0) is acquired. Continue to acquire data for channels 1 - 3.




Figure 7. OPEN Condition

Step 3. After the open correction measurements are completed, the following messages is displayed on the controller's display. The short correction data of each channel of the scanner (CH.0 - CH.3) is now measured.

CH.0 Short measurement
 Short test terminals of CH.0
 Start short meas. (2) Skip CH.0 short meas.?

Type number and press RETURN key

To measure the short correction data, set all channels to short condition as shown in figure 8. Then, type 1 and press the RETURN key on the controller. Short correction data of channel number 0 (CH.0) is acquired. Continue to acquire data for channels 1 - 3.

Step 4. After the open/short correction data is acquired, the following message (same as in step 1) is displayed on the controller's display.

Selection (1) Measurement (2) Correction?

Type number and press RETURN key

To execute the measurement, connect the multi-tap transformer under test to the scanner as shown in figure 9. Type 1 and press the RETURN key on the controller.




Figure 8. SHORT Condition

Self-inductance, dc resistance and turns ratio are measured by scanning each tap of the multi-tap transformer.

N1: L[H]: 6.00928E-6 DCR [OHM]: .0134568726173 N: 1
 N2: L[H]: 2.392557E-5 DCR [OHM]: .0171348134407 N: 2.1304
 N3: L[H]: 9.603832E-5 DCR [OHM]: .0230939715609 N: 4.0630
 N4: L[H]: .00038334126 DCR [OHM]: .0250939715609 N: 8.0188

Do you want to continue to measure (1) yes (2) no

Step 5. If you want to repeat the measurement, type 1 and press RETURN key on the controller. Or to end the program, type 2 and press RETURN key on the controller.

(D) Additional measurement error

The system configuration shown in figure 3, slightly increases measurement errors, in comparison with measured values using the 16060A transformer test fixture. These errors (supplemental characteristics) are the following using frequency: 1 kHz, signal level: 1 Vrms, measurement time: Medium.

Self-inductance: refer to figure 10
 Dc resistance: refer to figure 11
 Turns ratio: 0.02 % or less




Figure 9. Connection of multi-tap transformer

Appendix. Sample Program




Figure 10 . Self-Inductance additional error




Figure 11. Dc resistance additional error

Conclusion

By combining the Agilent 4263B (with Option 001) with a scanner, the required parameters of a multi-tap transformer can be measured with only one connection. Using this method improves efficiency at the production line or incoming inspection.

```

10  !*****
20  !* 4263B with Option 001
30  !* Transformer Measurement using scanner *
40  !*****
50  !
60  OPTION BASE 0
70  DIM Ch_hc(3),Ch_hp(3)
80  DIM Meas_r(3),Meas_l(3),Dummy(3),N(3),True_r(3),True_l(3)
90  DIM Open_r(3),Open_l(3),Open_g(3),Open_b(3),Short_r(3),Short_l(3)
100
110  4263B=717
120  3488a=709
130  Nch=3
140  F=1.0E+3
150  V=1
160  T=.065
170  N(0)=1
180
190  Main_menu:
200
210  PRINT CHR$(12)
220  Work=0
230  PRINT "SELECT FUNCTION (1) MEASUREMENT (2) CORRECTION ?" !
240  INPUT "TYPE NUMBER AND PRESS RETURN KEY",Work !
250  IF Work=1 THEN Measurement
260  IF Work=2 THEN Correction
270
280  Correction:
290
300  Open_correction:
310
320  OUTPUT 4263B;"SYSTEM:PRESET"
330  OUTPUT 4263B;"SOURCE:FREQ ";F
340  OUTPUT 4263B;"SOURCE:VOLTAGE ";V
350  OUTPUT 4263B;"SENS:FIMP:APER 0.5"
360
370  FOR Ch=0 TO Nch
380
390  Ch$=VAL$(Ch)
400  PRINT CHR$(12)
410  PRINT "CH."&Ch$&" OPEN MEASUREMENT"
420  IF Ch=0 THEN PRINT "OPEN TEST TERMINALS OF CH.0 AND CH.1" !
430  IF Ch<>0 THEN PRINT "OPEN TEST TERMINALS OF CH.0 AND CH."&Ch$ !
440  PRINT "(1) START OPEN MEAS. (2) SKIP CH."&Ch$&" OPEN MEAS.?"
450  Work=0
460  INPUT "TYPE NUMBER AND PRESS RETURN KEY",Work !
470  IF Work<=1 AND Work<=2 THEN 460
480  IF Work=1 THEN Open_meas
490  IF Work=2 THEN Open_skip_ch
500
510  Open_meas:
520
530  Ch_hc(Ch)=200+Ch*10
540  IF Ch=0 THEN Ch_hp(Ch)=211
550  IF Ch<>0 THEN Ch_hp(Ch)=201
560
570  OUTPUT 3488a;"RESET"
580  OUTPUT 3488a;"CLOSE";Ch_hc(Ch),Ch_hp(Ch)
590  OUTPUT 4263B;"SENS:FUNC:CONC ON"
600  OUTPUT 4263B;"SENS:FUNC 'IMP', 'RES'"
610  OUTPUT 4263B;"CALC1:FORM LS"
620  OUTPUT 4263B;"CALC2:FORM REAL"
630  OUTPUT 4263B;"TRIG:SOUR BUS"
640  OUTPUT 4263B;"*TRG"
650  ENTER 4263B;"S,Open_l(Ch),Open_r(Ch)
660  IF S<0 THEN 640
670  OUTPUT 3488a;"OPEN";Ch_hc(Ch),Ch_hp(Ch)
680  Open_g(Ch)=1/Open_r(Ch)
690  Open_b(Ch)=1/Open_l(Ch)
700
710  Open_skip_ch:
720
730  NEXT Ch
740
750  Short_correct:
760
770  OUTPUT 4263B;"SYSTEM:PRESET"
780  OUTPUT 4263B;"SOURCE:FREQ ";F
790  OUTPUT 4263B;"SOURCE:VOLTAGE ";V
800  OUTPUT 4263B;"SENS:FIMP:APER 0.5"
810
820  FOR Ch=0 TO Nch
830
840  PRINT CHR$(12)
850  Ch$=VAL$(Ch)
860  PRINT "CH."&Ch$&" SHORT MEASUREMENT" !
870  IF Ch=0 THEN PRINT "SHORT TEST TERMINALS OF CH.0 AND CH.1" !
880  IF Ch<>0 THEN PRINT "SHORT TEST TERMINALS OF CH.0 AND CH."&Ch$ !
890  PRINT "(1) START SHORT MEAS. (2) SKIP CH."&Ch$&" SHORT MEAS.?" !
900  Work=0
910  INPUT "TYPE NUMBER AND PRESS RETURN KEY",Work !
920  IF Work<=1 AND Work<=2 THEN 910
930  IF Work=1 THEN Short_meas
940  IF Work=2 THEN Short_skip_ch
950

```

```

960 Short_meas:
970
980 Ch hc(Ch)=200+Ch*10
990 IF Ch=0 THEN Ch hp(Ch)=211
1000 IF Ch<>0 THEN Ch_hp(Ch)=201
1010
1020 OUTPUT 3488a;"RESET"
1030 OUTPUT 3488a;"CLOSE";Ch hc(Ch),Ch hp(Ch)
1040 OUTPUT 4263B;"SENS:FUNC:CONC ON"
1050 OUTPUT 4263B;"SENS:FUNC 'IMP', 'RES'"
1060 OUTPUT 4263B;"CALC1:FORM LS"
1070 OUTPUT 4263B;"CALC2:FORM REAL"
1080 OUTPUT 4263B;"TRIG:SOUR BUS"
1090 OUTPUT 4263B;"*TRG"
1100 ENTER 4263B;S,Short_l(Ch),Short_r(Ch)
1110 IF S<>0 THEN
1120 OUTPUT 3488a;"OPEN";Ch hc(Ch),Ch_hp(Ch)
1130
1140 Short_skip_ch:
1150
1160 NEXT Ch
1170
1180 GOTO Main_menu
1190
1200 Measurement:
1210
1220 PRINT CHR$(12)
1230 OUTPUT 4263B;"SYSTEM:PRESET"
1240 OUTPUT 4263B;"SOURCE:FREQ ";F
1250 OUTPUT 4263B;"SOURCE:VOLTAGE ";V
1260 OUTPUT 4263B;"SENS:FIMP:APER ";T
1270 OUTPUT 4263B;"TRIG:SOUR BUS"
1280 OUTPUT 3488a;"RESET"
1290
1300 FOR Ch=0 TO Nch
1310
1320 OUTPUT 4263B;"SENS:FUNC:CONC ON"
1330 OUTPUT 4263B;"SENS:FUNC 'IMP', 'RES'"
1340 OUTPUT 4263B;"CALC1:FORM LS"
1350 OUTPUT 4263B;"CALC2:FORM REAL"
1360 Ch hc(Ch)=200+Ch*10
1370 IF Ch=0 THEN Ch_hp(Ch)=211
1380 IF Ch<>0 THEN Ch_hp(Ch)=201
1390 OUTPUT 3488a;"CLOSE";Ch hc(Ch),Ch_hp(Ch)
1400 OUTPUT 4263B;"*TRG"
1410 ENTER 4263B;S,Meas_l(Ch),Meas_r(Ch)
1420 True_l(Ch)=(Meas_l(Ch)-Short_l(Ch))/((1-(Meas_l(Ch)-Short_l(Ch))*Open_b(Ch)))
1430 True_r(Ch)=(Meas_r(Ch)-Short_r(Ch))/((1-(Meas_r(Ch)-Short_r(Ch))*Open_g(Ch)))
1440
1450 IF Ch=0 THEN Skip_meas
1460
1470 OUTPUT 4263B;"SENS:FUNC 'IMP', 'VOLT:AC"
1480 OUTPUT 4263B;"*TRG"
1490 ENTER 717;S,Dummy(Ch),N(Ch)
1500
1510 IF S=1 THEN
1520 OUTPUT 3488a;"OPEN";Ch hc(Ch),Ch_hp(Ch)
1530 Ch hc(Ch)=201+Ch*10
1540 Ch_hp(Ch)=200
1550 OUTPUT 3488a;"CLOSE";Ch hc(Ch),Ch_hp(Ch)
1560 OUTPUT 4263B;"*TRG"
1570 ENTER 4263B;S,Dummy(Ch),N(Ch)
1580 N(Ch)=N(0)/N(Ch)
1590 END IF
1600
1610 Skip_meas:
1620
1630 PRINT "N";Ch+1;"L [H]:";True_l(Ch),"DCR [OHM]:";True_r(Ch),"N:";N(Ch)
1640 OUTPUT 3488a;"OPEN";Ch hc(Ch),Ch_hp(Ch)
1650
1660 NEXT Ch
1670
1680 Work=0
1690 INPUT "DO YOU WANT TO CONTINUE TO MEASURE? (1) YES (2) NO",Work
1700 IF Work=1 THEN Measurement
1710 IF Work=2 THEN 1740
1720 IF Work<>1 AND Work<>2 THEN 1690
1730
1740 END

```

By internet, phone, or fax, get assistance with all your test and measurement needs

Online assistance:

www.agilent.com/find/assist

Phone or Fax:

United States:

(tel) 1-800-452-4844

Canada:

(tel) 1-877- 894-4414

(fax) (905) 282-6495

China:

(tel) 800-810-0189

(fax) 1-0800-650-0121

Europe:

(tel) (31 20) 547-2323

(fax) (31 20) 547-2390

Japan:

(tel) (81) 426-56-7832

(fax) (81) 426-56-7840

Korea:

(tel) (82 2) 2004-5004

(fax) (82 2) 2004-5115

Latin America:

(tel) (305) 269-7500

(fax) (305) 269-7599

Other Asia Pacific Countries:

(tel) (65) 375-8100

(fax) (65) 836-0252

Email: tm_asia@agilent.com

Product specifications and descriptions in this document subject to change without notice.

© Agilent Technologies, Inc. 1992, 2001

Printed in U.S.A., November 5, 2001

5091-6310E



Agilent Technologies